

PASSF 1.1.1.1
11/9/84
AA-2



ecology and environment, inc.

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 206-624-9537

International Specialists in the Environmental Sciences

M E M O R A N D U M

DATE: November 9, 1984

TO: Resource Recovery File

FROM: Peter Evers

SUBJ: Contact Report - Discussion on Containment

John Zillich of J-U-B Engineers returned my call. We discussed the containment measures used at each of the disposal sites at Resource Recovery in Pasco, Washington. He indicated that the containment was:

- o Wastes at Sites A,B,C and D were covered with a clear polyethylene sheeting (assumed to be 4 mil)
- o Wastes at Site E were placed on top of a similar liner and covered with another sheet of polyethylene.

PE:pc

